


High-V power line



RS232 or RS485



Direct 'plugged in' contact



Low-V power line




Ethernet



Electric wires for signal

# Inside of the GHS electronics box



Incoming 3-phase power



# Ethernet to NIKA2 network



## RS485 to PTs

## 3-phase to PTs



## NIKA2 3phase power plug

NIKA2 compressed air is plugged inside the spiral room